



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 9th May, 2016

Dear Customer,

Re: Product Change Notification for Harwin product.

Please be advised that the following ranges have been affected by Technical Drawing changes since June, 2015:

- M22-634XX42

The changes from issue 13 to issue 15 on M22-634XX42 are as follows:

- Issue 14: Contact Point dimension added on customer drawing.
- Issue 15: Sizes 21 per row to 25 per row made obsolete. Holes added to PCB layout (required when product is used as a bottom-entry connector, or extra-long male mating pins are used in top-entry) – these holes were already on the drawing for M22-634XX42R, the tape and reeled version, but had previously been missing from this drawing. The pad dimensions have not changed.

The connector design itself is unchanged from issue 13 to 15.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com