

20 February 2026

Dear Customer,

Re: Product Change notification for Harwin product.

There has been a change to the tape pocket on the following products:

Part Number(s)	Tape Width change	Technical Drawing
M55-6021242R M55-6021642R M55-6071242R M55-6071642R	From 24mm to 32mm	https://content.harwin.com/m/62649baf7a8e0cb3/original/DRG-02766-Technical-Drawing-Datasheet-M55-60X-pdf.pdf

Please see the latest Technical Drawing following the above link.

Any further modifications to the tape are limited to those necessary to accommodate the increased tape width in accordance with EIA-481, including the addition of a second row of sprocket holes. The components are not affected and remain unchanged.

This change improves packaging efficiency on our production lines.

All new and existing orders at Harwin will be supplied in the new tape width. Reels with the new tape width will be clearly labelled for a minimum of 12 months. Using the new design will require a change to your Pick/Place machine setup to accept the wider tape width.

As stock filters through our Distribution network, you may still receive the old design in the short term.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
support@harwin.com