



02 September 2024

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete with immediate effect:

- G125-XP1XXXXXXX

All affected part numbers from this range have been replaced with a new longer part number. The parts will be identical; only the part number has been replaced.

- G125-XP1XXXXAAXXXXX

Please see the next page for a detailed list of currently affected items and their replacement part numbers.

This change in the part numbering system has been introduced to allow for a wider range of options for this range. Once existing stocks of the previous part numbers have been depleted, all new orders will need to use the replacement numbering system.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
support@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Last Time buy date	Alternative product	Drawing for alternative product
G125-FP10060F94	Immediate	G125-FP10060AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-FP10150F94	Immediate	G125-FP10150AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-FP10150L94	Immediate	G125-FP10150AAL9400	G125-XP1XXXXAAXXXXXX.pdf
G125-FP10300F94	Immediate	G125-FP10300AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-FP10300L94	Immediate	G125-FP10300AAL9400	G125-XP1XXXXAAXXXXXX.pdf
G125-FP10450F94	Immediate	G125-FP10450AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-FP10450L94	Immediate	G125-FP10450AAL9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10060M94	Immediate	G125-MP10060AAM9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10150F94	Immediate	G125-MP10150AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10150L94	Immediate	G125-MP10150AAL9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10150M94	Immediate	G125-MP10150AAM9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10300F94	Immediate	G125-MP10300AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10300L94	Immediate	G125-MP10300AAL9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10300M94	Immediate	G125-MP10300AAM9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10450F94	Immediate	G125-MP10450AAF9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10450L94	Immediate	G125-MP10450AAL9400	G125-XP1XXXXAAXXXXXX.pdf
G125-MP10450M94	Immediate	G125-MP10450AAM9400	G125-XP1XXXXAAXXXXXX.pdf